

Report No. : PN:EE:1456003840

ISSUE DATE : 17/05/2024



AP LANKA (PVT) LTD
416/5, LEYLAND ROAD
Homagama-10200
LK

CONTACT PERSON : HARSHA DULIP

THE FOLLOWING SAMPLE(S) WAS/WERE SUBMITTED AND IDENTIFIED BY/ON BEHALF OF THE CUSTOMER AS :

SAMPLE DESCRIPTION MODIK Wall Mounting Box Enclosure
PART NO 795 030
COLOUR RAL 7035
OEM OTHERS
COUNTRY OF ORIGIN Sri Lanka
DATE OF REGISTRATION 30/12/2023
TEST(S) REQUESTED SALT MIST TEST

TESTING PERIOD : 24/04/2024 – 03/05/2024

Test name	Test method
Salt mist test	IEC 60068 – 2 - 11 : 2021 AS specified by the customer

Contents

1.	Summary :	2
2.	List of figures :	3
3.	General definitions :	3
4.	DUT Information :	4
5.	Salt mist test	5
	5.1 Test condition :	5
	5.2 No. of DUT's :	5
	5.3 Observation table :	5
	5.4 Test photographs :	6
6.	Equipment details :	7



1. Summary :

Test name	Test method	No. of DUT	Testing period	Result	Remark
Salt mist test	IEC 60068 – 2 - 11 : 2021 AS specified by the customer	01	24/04/2024 to 03/05/2024	Pass	Tested samples meets the test requirement

Note : Test performed as per the conditions given by the customer.

**2. List of figures :**

Figure 01	DUT as received
Figure 02	DUT in chamber
Figure 03	Test chamber
Figure 04	DUT after test

3. General definitions :

DUT	Device under test
s	Second
min	Minute
A	Ampere
mV	Millivolt
mA	Milliampere
Hrs.	Hours
MΩ	Megaohm



4. DUT Information :

DUT Name	MODIK Wall Mounting Box Enclosure
Part No	795 030
H/w number	--
s/w number	--
No. of DUT	01
DUT operating voltage	--
DUT condition	DUT received in good condition



Fig 1 – DUT as received



5. Salt mist test

Test method: IEC 60068 – 2 - 11 : 2021 As specified by customer.

5.1 Test condition :

Test conducted as per below condition and sequence.

Sr. No	Parameter	Specification
1	Salt Solution Concentration	(50 ± 5) g/l
2	Chamber Temperature	(35 ± 2)°C
3	pH of fog solution	6.5 – 7.2
4	Fog Collection	1.5 ± 0.5 ml/hr
5	Test duration	200 Hours

5.2 No. of DUT's :

1

5.3 Observation table :

Time intervals (Hours)	Visual observation
24	No sign of rust observed
48	No sign of rust observed
72	No sign of rust observed
96	No sign of rust observed
120	No sign of rust observed
144	No sign of rust observed
168	No sign of rust observed
192	No sign of rust observed
200	No sign of rust observed



5.4 Test photographs :



Fig 02 – DUT in chamber



Fig 03 – Test chamber



Fig 04 – DUT after test



6. Equipment details :

Equipment name	Equipment ID	Equipment make	Calibration due date
Salt Spray Chamber	TRP (CHN)/SS-127	ASCOTT	04/04/2025

***** End of Report*****

Confidential Business Information

Authorized Signatory

Mishra Durga
(Asst. Manager)mail your Test Report Related Enquiries at Feedback.trp@sgs.com